

2-25-14 2 1/2 " Main Line Hiter Road

This line crossing a bridge a natural drainage ditch on Hiter Road was shot. This line was fixed by (b) (6). There were shell casings found on scene collected by (b) (6), (b) (6). This line was not incased in a steel casing.

2-25-14

Water samples were pulled system wide from all 6 wells. A total of 6 samples were dropped off at the Bolivar County Health Department. These samples were signed in by (b) (6), (b) (6) Operator and left in an entry hall to the Health Department.

2/27/14

(b) (6), Operator received a phone call from Mississippi State Department of Health from (b) (6) stating all 6 samples were E-Coli positive. (b) (6), started pulling samples per (b) (6) direction this date and for the next 3 days. All new samples came back clear.

3-27-14 Litton Road

Water line crossing 1st bridge on Litton Road west of Shaw Skene Road was vandalized. This pipe was exposed without a casing. There were pieces of concrete blocks on the side of the ditch in the grass. (b) (6), (b) (7)(C) saw a clear path were someone walked thru the tall grass to the pipe. It appeared a piece of the concrete was used to bust the water line. This line was repaired by (b) (6) under (b) (6), (b) (6) supervision. (b) (6), received a call at approx. 4:30 Am from the first customer stating they had no water. By looking at telemetry system leak occurred at approx. 2:45AM

5-4-14 Walker Road

(b) (6), (b) (6) Operator began receiving calls from customers in the Walker Road area about no water. After searching, a leak was found on the South side of Walker Road. This line crosses a small drainage ditch approximately fifteen feet off the roadway. This line is a four inch main line and appeared to have been broken by a hammer or hatchet type tool. (b) (6), was called and the line was repaired.

5-28-14 Malvina Road

A line that was inches underground was busted with what appears to be a hatchet or ax type tool. This leak was repaired by (b) (6), (b) (6).

6-7-14 Litton Road

(b) (6), (b) (7) started receiving calls of no water around 12:30 PM. (b) (6), (b) (7) was called to help find a leak and after 4 hours of searching for a water leak we found a 6" water line crossing a natural drainage ditch off the West side of Shaw Skene Road north of Litton Road. This line was only accessible from the turn row going around the field and had been shot. Phillips Plumbing Company and Bayou Pipeline Company repaired this leak. See report from Bolivar SO.

7-4-14 Litton Road

(b) (6), (b) (7) started receiving calls from customers with no water at approx. 4:30 AM. Operator (b) (6), (b) (7) contacted (b) (6), (b) (7) and advised him to start checking for problems at the Benoit tower. The tower was found to be completely drained. Phillips plumbing was then contacted to assist in locating a leak that could have caused this problem. (b) (6), (b) (7) with Phillips Plumbing found a 10" water line on the 1st bridge on Litton Road East of HWY 448 was leaking and had been shot. This line is incased in a steel casing. This line feeds many customers including the Benoit Outing Club. The weekend of July 4th is one the busiest weekends for the Benoit Outing Club when the most people were in cabins for the weekend. This leak resulted in the entire Benoit system being down for the entire weekend. This water line was repaired by Phillips Plumbing and Bayou Pipeline Company. The water was restored to customers at approx. 8:00 PM on July 5, 2014. Bolivar SO was called and an officer came on scene.

7-31-14 HWY 448

(b) (6), (b) (7) called in with low water pressure this morning. (b) (6), (b) (7) found a water leak at an abandon meter on Hwy 448 around a flying strip. The line feeding this meter was busted. See MBI report. Leak was repaired by (b) (6), (b) (7)

8-5-14 Oneal Road

(b) (6), (b) (7) called (b) (6), (b) (7) to report water around a cemetery on Oneal Road. A water line going to a bleed off valve at a cemetery was vandalized with what appeared to be a probe rod. This line was repaired by (b) (6), (b) (7). (b) (6), (b) (7) called later that afternoon with low water pressure on Oneal Road.

8/5/14 Oneal Road

A second bleed off valve on Oneal Road was also vandalized the same day. This line was also going to bleed off valve and was busted with what appeared to be a probe rod. (b) (6), (b) (7) repaired this leak.

8-12-14 Hwy 61

Water was seen standing on side of Hwy 61. The main water line on East side of Hwy 61 underground was hit with what appeared to be a probe rod. This leak was repaired by (b) (6), (b) (7)

8-18-14 Litton Road

Customers call complaining of low water pressure on Litton Road. (b) (6), (b) (7) found the main water line crossing the bogue bridge was vandalized. This line is attached to the bridge thru steel casing. The line was hit on the west side of the bridge where the steel casing ends. This same line was repaired by (b) (6), (b) (7) several years ago when it separated at a joint. We did find a knock on where (b) (6), (b) (7)

repaired the line inches from where it was chopped with what appears to be a hatchet. See MBI report. Line repaired by (b) (6), (b) (7).

9/1/14 White Street

Customer called in with low water pressure. A line crossing a ditch on White Street just East of Delta Wells road was shot thru steel casing. Bolivar SO was called Deputy Sheriff (b) (6), (b) (7) came on scene and did report. Later this week (b) (6), (b) (7) saw (b) (6), (b) (7) sitting on this bridge looking at repair job. (b) (6), (b) (7) with (b) (6), (b) (7) and was told by (b) (6), (b) (7) that he was just looking for farm land to rent. (b) (6), (b) (7) later filed stalking charges on (b) (6), (b) (7) using this incident as stalking. (b) (6), (b) (7) repaired this leak. See SO report.

9/2/14 Fraizer Road

While we were repairing the line on the White Street bridge we received a call from (b) (6), (b) (7) in Malvina at approx. 8:30 PM. She stated she did not have water. (b) (6), (b) (7) began looking for a leak. He found a water line crossing a bridge on Fraizer road thru a steel casing was shot. We finished repairing leak on White Street and moved on to leak on Fraizer Road. Bolivar SO was called and Deputy Sheriff (b) (6), (b) (7) came on scene for report. (b) (6), (b) (7) fixed leak.

9/10/14 Odom Road

(b) (6), (b) (7) received calls from customers without water on Hwy 61 North and Tolivar Road. As we were looking for leak (b) (6), (b) (7) followed fresh tire tracks into a freshly disk field to a tree line. Leading into the tree line was what appeared to be a path where someone walked into the woods. (b) (6), (b) (7) followed the trail leading to a exposed water line crossing a small ditch the PVC pipe was shot. (b) (6), (b) (7) fixed the line. Bolivar County SO was called and Deputy Sheriff (b) (6), (b) (7) came to scene.

9/21/14 Niblett Road Bridge

(b) (6), (b) (7) at (b) (6), (b) (7) called she did not have water. She said she was watering dogs and water went off. She was only customer that called. We found water line in steel casing crossing bridge just west of Pearson Road was shot. This line only feeds the house of (b) (6), (b) (7)(C) fixed leak.

11/3/14 Litton Road

We received calls from Litton area with low water pressure. (b) (6), (b) (7) found Pipe in Steel casing crossing 2nd bridge past Shaw Skene Road was shot. (b) (6), (b) (7) fixed this leak. Bolivar SO was called an officer came on scene.

11/9/14 White Star Road

(b) (6), (b) (7) received calls from customers this morning with low water pressure on White Star Road. He found a bleed off valve that had been hit with what appears to have been a probe rod. As he was looking at the leak (b) (6), (b) (7) rode by and laughed at him. (b) (6), (b) (7) fixed the leak.

11/9/14 White Street-Old Ruleville Road

This afternoon we began receiving calls from customers in Noblin subdivision with low water pressure. We found a 4" water line crossing a ditch at intersection of White Street and Old Ruleville Road had been shot. (b) (6), (b) (7) fixed this line. Bolivar SO was called an officer came on scene.

11/10/14 Herbison Road

(b) (6), (b) (7)(C) called at approx. 6:30Am with low water pressure. (b) (6), road down to an old house site past his house and found a service line going to an abandon meter for an old house was hit with what appeared to be a probe rod. (b) (6), (b) (7)(C) (board member for Boyle Skene Water) lives (b) (6), (b) (7)(C) stated that he heard traffic on this road several times that night. He is the only house that is occupied on this road and very rarely has traffic this time of year. (b) (b) that also lives in the house with (b) (6), (b) said he saw a dark colored diesel truck pass the house several times that night. (b) (6), (b) (7) fixed this leak. Bolivar SO was called an officer came on scene after the repairs had been made.

11/10/14 Intersection of Smith Road and Parks Road

Also, this morning we received a call that water was seen at the intersection of Smith and Parks road. We went to find an underground water line has been hit with what appeared to be a probe rod just inside the turn row in field. While we were fixing leak on Smith-Parks (b) (6), received a call from (b) (6), (b) (b) passed (b) (6), (b) on Litton Road, watched him go to Dummy Line road, and stop on the Bridge for approx. 15 min. Boyle Skene Water does not have a water line that crosses that bridge. Approx an hour later, as we finished fixing this leak (b) (6), (b) came thru the intersection while we were still loading up parts and equipment. (b) (6), (b) (7) fixed leak and drove North on Smith Road to locate a bleed of valve in order to flush the system beyond the leak site. Shortly after this incident is when (b) (b) was arrested by the Bolivar County Sheriff's Office on a warrant for Stalking issue by the Bolivar County Justice Court. Bolivar SO was called an officer came to scene.

10/10/14 HWY 448

(b) (6), (b) (7) called approx. 1 ½ hours after we finished the leak on Smith-Parks to report no water at his house on Hwy 448. We went to bridge just West of Dummy Line road and found another water line had been shot. This was a 6" line thru steel casing. Bolivar SO was called and report was made. (b) (b) (b) fixed leak.

11/20/14 Dixon Road

Customer called on Chisolm Road without water since approx. 5:00AM. We found water line crossing ditch on Dixon road was shot. Bolivar SO called officer (b) (b) took report, he stated an investigator would call within the hour to investigate. Never received a call from investigator. (b) (6), (b) (7) fixed leak.

11/23/14 Fraizer Road

(b) (6), (b) (7) called with low water pressure around 6:15AM no one else called and when we contacted (b) (6), (b) (7) again she said her pressure was better. However, She called back later that afternoon saying pressure was very low again. We found a line underground at the intersection of Fraizer and Walton Road was hit with what appeared to be a probe rod. Bolivar SO was called however, there was not an officer available and dispatcher said she would write report since she writes them anyway. (b) (6), (b) (7) fixed leak.

11/23/14 Sandpit Road

Customer called at approx. 10:00 Am stating water was coming up from ground at the intersection of Sandpit and Gibert Road. We found a water line underground that had been hit with what appeared to be a probe rod. Bolivar SO was called a female black officer came on scene. (b) (6), (b) (7) fixed leak.

12/6/14 Litton Bridge

Water line on 2nd Bridge on Litton Road west of Shaw Skene Road was shot a 2nd time. It started raining and the pipe was under water before we could fix the line. We strung temp line across banks since we could not get to old line to repair. 12/9/14 We called (b) (6), (b) (7), with Bayou Pipeline Company, to bring a big trackhoe to help dig the line out so we could repair it. We buried the line underground in bottom of ditch. Since then the line has washed and is exposed again. (b) (6) Fixed leak with help of (b) (6), (b) (7). Bolivar SO was called and came on scene. 12/10/14 (b) (6), (b) (7)(C) saw (b) (6), (b) (7) sitting on the bridge looking at repair.

12/12/14 Ralph Ray Road

The water line at Bridge on Ralph Ray Road past (b) (6), (b) (7) house was vandalized sometime between 4:30 PM and 7:00PM. This is not a Boyle Skene Water line. This line is property of Sunflower Water Association. (b) (6) is the only house past the bridge that was vandalized. No police report was filed since this was not a Boyle Skene Water line. (b) (6), (b) (7) maintainece man for Sunflower water, spoke with (b) (6) he said they have not had cases of vandalized lines but he believed this line was vandalized.

12/23/14 Jones Road

(b) (6), (b) (7), President of Boyle Skene Water Assn, called at approx. 10:00Am stating he had low water pressure that morning. A bleed off valve on Jones road was found leaking with what appeared to have been vandalized with a probe rod. This valve was in the yard at (b) (6), (b) (7). However, when we fixed the line on one was home at this residence. Sunflower So was called and came to scene. (b) (6), (b) (7) fixed leak.

12/31/14 Hwy 446

(b) (6), (b) (7) board member for Boyle Skene Water, called saying there was water flooding an empty lot next to (b) (6), (b) (7) old house at (b) (6), (b) (7). (b) (6) found an old abandon meter was vandalized with

what appeared to be a probe rod. (b) (6), (b) (7) fixed leak. Bolivar SO was called an officer came on scene.

12/31/14 Pearson Road

(b) (6), (b) (7) on Niblett road called with low water pressure again. We found a water line crossing bridge on Pearson Road North of Niblett Road was shot thru steel casing. This line only feeds one house and a farm headquarters. However, it created water loss to (b) (6), (b) (7) on Niblett road. (b) (6), (b) (7) fixed leak. Bolivar So was called and Officer (b) (6), (b) (7) arrived on scene.

1/8/15 HWY 448

Several lines were shot on this date causing major issues with the Benoit Well keeping up with the demand of water usage. This line was shot crossing a bridge in steel casing ¼ mile west of Palmer Satterfield Road. This line only feeds one shot and customer is not using water at this time. We have not repaired this leak at this time. (b) (6), (b) (7) with MBI was called to add this incident to his report.

1/8/15 Hwy 1

Line was shot in ditch going thru steel casing on side of Hwy 1 South of Hwy 446. This line was only accessible by the turn row on the side of the Hwy. (b) (6), (b) (7) repaired water line. This leak was repaired on this date however, it separated again on 1/11/14 while repairing this leak a 2nd time (b) (6), (b) (7) saw (b) (6), (b) (7) and (b) (6), (b) (7)(C) ride past in a Black Chevy truck while the repairs were being made. (b) (6), (b) (7) with MBI was called to add this incident to his report.

1/8/15 Hwy 446

Line was shot on Hwy 446 in 1st ditch east of Hwy 1 thru steel casing. This was the 3rd line that was shot that night. (b) (6), (b) (7) fixed leak. However, this line separated again on 1/11/14 while repairing this line the 2nd time (b) (6), (b) (7) and (b) (6), (b) (7)(C) rode by in a black Chevy truck. (b) (6), (b) (7) took video of them passing the scene. This side is located approx. 1 mile from previous Hwy 1 leak from this night. (b) (6), (b) (7), MBI, was called to add this to his report.

1/14/14 Evans Road

At approx. 8:30 calls began coming in for low water pressure. (b) (6), (b) (7) found a water line thru steel casing was shot at the intersection of Evans road and Crosby Road. (b) (6), (b) (7) fix leak. Trail cam was place at the site of the leak. Trail Cam pics show (b) (6), (b) (7) at the leak site looking at the repairs on 1/15/14. However, the trail cam was misdated to 12/15/14. Bolivar SO was called an officer came to scene.

2/3/15

Approx. 8:30 PM (b) (6), (b) (7)(C), board member for Boyle Skene Water, saw a dark color truck turn off Litton Road traveling North on Herbison Road toward his house. He said it that like a diesel

truck. This truck was halfway to (b) (6), house from intersection when the driver turned the lights off. This was a full moon night. The truck kept driving slowly toward the house, then backed up to turn row where it stopped for approx. 5 min, then came back toward the house. This time the truck stopped at the end of (b) (6), house where there was a view of the inside of the house thru the front windows, with lights off. (b) (6), and his family was in that front room at the time the truck was in front of the house. The truck backed up approx. ¼ mile to the turn row, turned around, and went back North the same way it came to Litton Road.